Update-Description
inLab CAM SW 22.2.0

This document describes changes and improvements compared to previous version inLab CAM SW 22.1.0

Date: September 2022

Dentsply
Sirona

General

New features

- Installation Wizard includes Dentsply Sirona System Monitor 1.1
- inLab CAM SW prepared to receive production jobs from DS Core
  (requires Dentsply Sirona System Monitor 1.4)

New materials

- Kuraray Noritake: KATANA Zr ONE
- GC: New shades for CERASMART materials
- Dentsply Sirona: CEREC Tessera abutment: geometry update

New Device Firmware

Primemill:

- Quality and stability improvements, e.g.

  - Improved surface quality for super-fast milling

  - Bug fixes concerning milling artefacts on e.g. meso abutments

Primeprint:

- Improved print accuracy/trueness of dental models (overhang correction)
- New Firmware for Primeprint and PPU
- Primeprint Firmware with the option to connect with DS Core
- Primeprint Firmware with screensaver
  (Display turns black after a few minutes and can be activated by touching)

SpeedFire

- New demo programs for CEREC SpeedFire

Quality improvement and stability

Dentsply Sirona continuously improves the quality of its products. As part of this release, several improvements have been made and known software bugs have been fixed. We always recommend using the latest software version.

Procedural Solutions

Preventive
Restorative
Orthodontics
Endodontics
Implants
Prosthetics

Enabling Technologies

CAD/CAM
Imaging
Treatment Centers
Instruments

Dentsply Sirona

Sirona Dental Systems GmbH
Fabrikstraße 31, 64625 Bensheim, Germany
dentsplysirona.com

THE DENTAL
SOLUTIONS
COMPANY™

Dentsply
Sirona