

Service Pack inLab CAM 16.2 Update Description inLab CAM 16.2

This document explains the changes of Service Pack inLab CAM 16.2 to inLab CAM 16.1.

April 2018



THE DENTAL SOLUTIONS COMPANYTM

inLab CAM SW 16.2 April 2018; Changes to inLab CAM 16.1

Calibration

The calibration process has been improved as such, that the location of the tool magazine is captured more precisely.

Tool Wear

The prediction of remaining tool life has been improved.

Data Import

The import of *.stl and exocad data has been improved.

Bugfixes

Dentsply Sirona continuously improves the quality of products. With a software service pack, improvements are implemented and known software bugs are removed. We recommend working with the latest software version.