

Update-Description in Lab Model 19.1

This document describes changes and improvements compared to previous version inLab Model 19.0

September 2019



Following topics have been corrected

- Problem solved with rotated MIS analogs
- Problem solved with the form tool being unavailable
- Problem solved when creating analogs from multilayer abutment cases
- Problem solved with software crashing during model base calculation
- Problem solved when creating multiple non-removable dies

Quality improvement and stability

Dentsply Sirona continuously improves the quality of its products. As part of this release, several improvements have been made and known software bugs have been fixed. We always recommend using the latest software version.